

## Replacement for OE 2007+ Bellows Section

### Freightliner/Western Star

PART NO.	SIMILAR TO	DIAMETER
FL-27334-018	A04-27334-18 OR A04-26200-018	5"
FL-28522-000	A04-28522-000 OR A04-25022-018	5"
FL-28578-000	04-28578-000 OR A04-25922-018 OR A04-26193-018	4"



### International/Navistar

PART NO.	SIMILAR TO	DIAMETER
IH-1755C4	3811775C4	4" & 5"
IH-8113C5	3628113C5	4" & 5"
IH-6294C2	3826294C2	4" & 5"
IH-0024C3	3820024C3	4" & 5"



### Paccar/Kenworth/Peterbilt

PART NO.	SIMILAR TO	DIAMETER
KW-6559	M66-6559	2.5"
KW-6541-0320	M66-6541-0320	4"
KW-6541-0335	M66-6541-0335	4"
KW-6541-0405	M66-6541-0405	4"
KW-6542-0320	M66-6542-0320	5"
KW-6542-0335	M66-6542-0335	5"



### Volvo/Mack

PART NO.	SIMILAR TO	DIAMETER
VG-1403	21051403	5"
VG-8532	21428532	5"
VG-8534	21428534	4" & 5"

